

## MIAMI-DADE COUNTY BUILDING DEPARTMENT INSPECTIONS REJECTION RATE Business Plan FY 2007-2008 From October 2007 to September 2008

TRADE	OCTOBER						NOVEMBER						DECEMBER						JANUARY					
	*TOTAL	APPROVED	CARRYOVERS & BAD WEATHER	*** INVALID INSPECTION REQUEST	REJECTED	% REJECTION	*TOTAL	APPROVED	CARRYOVERS & BAD WEATHER	*** INVALID INSPECTION REQUEST	REJECTED	% REJECTION	*TOTAL	APPROVED	CARRYOVERS & BAD WEATHER	*** INVALID INSPECTION REQUEST	REJECTED	% REJECTION	*TOTAL	APPROVED	CARRYOVERS & BAD WEATHER	*** INVALID INSPECTION REQUEST	REJECTED	% REJECTION
Building	8,883	6,987	59	450	1,896	21	8,160	6,543	1	294	1,617	20	6,778	5,284	2	296	1,494	22	7,132	5,621	10	310	1,511	21
Electrical	5,242	3,861	8	349	1,381	26	5,117	3,719	1	303	1,398	27	4,588	3,238	0	275	1,350	29	4,698	3,295	0	275	1,403	30
Mechanical	1,636	1,202	3	99	434	27	1,579	1,156	3	95	423	27	1,353	937	5	80	416	31	1,605	1,127	12	89	478	30
Plumbing	3,606	2,700	11	179	906	25	3,132	2,396	0	123	736	23	2,494	1,839	2	137	655	26	2,800	2,041	3	107	759	27
Roofing	3,698	2,811	43	297	887	24	3,825	2,811	1	189	1,014	27	3,200	2,404	2	185	796	25	3,116	2,418	4	143	698	22
LPGX	5	3	0	0	2	40	7	4	0	3	3	43	9	6	0	0	3	33	1	0	0	0	1	100
Sign	305	210	0	22	95	31	237	191	1	34	46	19	166	120	0	23	46	28	220	162	0	32	58	26
<b>TOTAL</b>	<b>23,375</b>	<b>17,774</b>	<b>124</b>	<b>1,396</b>	<b>5,601</b>	<b>24</b>	<b>22,057</b>	<b>16,820</b>	<b>7</b>	<b>1,041</b>	<b>5,237</b>	<b>24</b>	<b>18,588</b>	<b>13,828</b>	<b>11</b>	<b>996</b>	<b>4,760</b>	<b>26</b>	<b>19,572</b>	<b>14,664</b>	<b>29</b>	<b>956</b>	<b>4,908</b>	<b>25</b>

TRADE	FEBRUARY						MARCH						APRIL						MAY					
	*TOTAL	APPROVED	CARRYOVERS & BAD WEATHER	*** INVALID INSPECTION REQUEST	REJECTED	% REJECTION	*TOTAL	APPROVED	CARRYOVERS & BAD WEATHER	*** INVALID INSPECTION REQUEST	REJECTED	% REJECTION	*TOTAL	APPROVED	CARRYOVERS & BAD WEATHER	*** INVALID INSPECTION REQUEST	REJECTED	% REJECTION	*TOTAL	APPROVED	CARRYOVERS & BAD WEATHER	*** INVALID INSPECTION REQUEST	REJECTED	% REJECTION
Building	6,816	5,185	21	327	1,631	24	6,693	5,088	8	291	1,605	24	7,718	5,887	3	390	1,831	24	7,134	5,364	3	376	1,770	25
Electrical	4,289	3,101	2	267	1,188	28	4,427	3,124	1	301	1,303	29	4,786	3,379	0	270	1,407	29	4,426	3,092	5	332	1,334	30
Mechanical	1,385	943	9	88	442	32	1,353	949	24	71	404	30	1,471	1,041	30	79	430	29	1,408	975	42	78	433	31
Plumbing	2,791	1,953	3	140	838	30	2,692	2,013	2	157	679	25	3,098	2,364	0	149	734	24	2,594	1,940	0	99	654	25
Roofing	3,030	2,272	4	127	758	25	3,127	2,292	8	126	835	27	3,521	2,590	0	137	931	26	3,263	2,157	16	210	1,106	34
LPGX	1	0	0	1	1	100	10	8	0	1	2	20	5	2	0	0	3	60	3	3	0	2	0	0
Sign	272	190	0	22	82	30	221	180	0	16	41	19	195	140	0	17	55	28	262	193	0	23	69	26
<b>TOTAL</b>	<b>18,584</b>	<b>13,644</b>	<b>39</b>	<b>972</b>	<b>4,940</b>	<b>27</b>	<b>18,523</b>	<b>13,654</b>	<b>43</b>	<b>963</b>	<b>4,869</b>	<b>26</b>	<b>20,794</b>	<b>15,403</b>	<b>33</b>	<b>1,042</b>	<b>5,391</b>	<b>26</b>	<b>19,090</b>	<b>13,724</b>	<b>66</b>	<b>1,120</b>	<b>5,366</b>	<b>28</b>

TRADE	JUNE						JULY						AUGUST						SEPTEMBER					
	*TOTAL	APPROVED	CARRYOVERS & BAD WEATHER	*** INVALID INSPECTION REQUEST	REJECTED	% REJECTION	*TOTAL	APPROVED	CARRYOVERS & BAD WEATHER	*** INVALID INSPECTION REQUEST	REJECTED	% REJECTION	*TOTAL	APPROVED	CARRYOVERS & BAD WEATHER	*** INVALID INSPECTION REQUEST	REJECTED	% REJECTION	*TOTAL	APPROVED	CARRYOVERS & BAD WEATHER	*** INVALID INSPECTION REQUEST	REJECTED	% REJECTION
Building	6,719	5,098	37	311	1,621	24	7,177	5,467	22	309	1,710	24	6,212	4,677	195	346	1,535	25	6,338	4,859	14	372	1,479	23
Electrical	4,307	3,318	14	243	989	23	4,785	3,877	1	272	908	19	4,097	3,335	81	229	762	19	4,512	3,729	5	216	783	17
Mechanical	1,315	937	12	80	378	29	1,360	959	5	89	401	29	1,160	803	24	72	357	31	1,311	915	13	83	396	30
Plumbing	2,681	1,939	9	132	742	28	2,892	2,103	5	136	789	27	2,665	1,917	76	130	748	28	2,481	1,768	7	116	713	29
Roofing	2,980	2,157	34	149	823	28	3,304	2,483	13	165	821	25	2,560	1,870	57	159	690	27	2,629	1,962	23	138	667	25
LPGX	8	4	0	0	4	50	7	3	0	0	4	57	1	1	0	0	0	0	2	2	0	0	0	0
Sign	215	182	1	22	33	15	202	165	0	17	37	18	222	194	1	22	28	13	296	254	0	24	42	14
<b>TOTAL</b>	<b>18,225</b>	<b>13,635</b>	<b>107</b>	<b>937</b>	<b>4,590</b>	<b>25</b>	<b>19,727</b>	<b>15,057</b>	<b>46</b>	<b>988</b>	<b>4,670</b>	<b>24</b>	<b>16,917</b>	<b>12,797</b>	<b>434</b>	<b>958</b>	<b>4,120</b>	<b>24</b>	<b>17,569</b>	<b>13,489</b>	<b>62</b>	<b>949</b>	<b>4,080</b>	<b>23</b>

\* Total Includes Approved and Rejected Inspections

\*\*\* Invalid Inspection Request includes no access, unable to locate, plan and permit missing

